

FOR SPAS PRIOR TO 2019 - IN ORDER FOR YOUR SPA TO OPERATE PROPERLY: **THE EAGLE IQ2020, WIRELESS REMOTE AND DOCK MUST BE RUNNING THE SAME VERSION OF SOFTWARE**

Dock software is installed via the USB port on the motherboard, just like the control box software file.

Dock Software:
DK4.00



(PN 78509)
Dock

Remote software must be installed via the Programmer

Remote Software:
RM4.00



(PN 77472)

Remote Programmer

IQ2020 software is installed via the USB port on the motherboard.

IQ2020 Software:
WR4.04



(PN 76836)

IQ2020 Control Box

When replacing the Dock you must update the Remote & IQ2020 Software



(PN 78504)
Remote

When replacing the Remote you must update the Dock & IQ2020 Software

When replacing the IQ2020 you must update the IQ2020 software to match the version of your remote and dock.